

CONSTRUCTION INSPECTION SERVICES

Fire Station No. 2
5420 Main Street
Downers Grove, Illinois 60515

CLIENT / CONTACT

Owners Service Group
Ed Disler
1815 South Meyers Road, Suite 200
Oakbrook Terrace, Illinois

OWNER

The Village of Downers Grove

Owners Services Group, Inc. enlisted GEOCON to perform construction testing and inspection services for the new 33,000 square foot Fire Station No. 2 building, to replace the original fire station, which was at the same site.

The new building provides many improvements and benefits, including two heating systems for greater efficiency and economy. Careful consideration was given in planning for storage and maintenance facilities for the hoses as well as to the lighting and comfort of the living quarters

Partially Listing of Services Provided:

- Verified footing subgrade strength
- Soil and aggregate compaction testing
- Fresh concrete testing and monitoring
- Compressive strength testing
- Subgrade strength testing
- Proofroll tests

